

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|-----|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00076-000 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1800 | — | 400 |
| 065-00083-000 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1750 | — | 400 |
| 065-00085-000 | — | — | 2X13X1550 | — | 400 | — | — | — |
| 065-00090-000 | — | — | POLY V 4PK 860 | — | 600 | — | — | — |
| 065-00114-000 | — | — | POLY V 6PK 2345 | — | 600 | — | — | — |
| 065-00116-000 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1800 | — | 400 |
| 065-00116-001 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1750 | — | 400 |
| 065-00126-000 | — | — | TORQUE TEAM 2/BX89 | — | 400 | 2X13X1625 | — | 80 |
| 065-00133-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00134-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00136-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1625 | — | 80 |
| 065-00150-000 | — | — | TORQUE TEAM 13AV1400 | — | — | — | — | — |
| 065-00156-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00160-000 | — | — | TORQUE TEAM 13AV1400 | — | — | — | — | — |
| 065-00163-000 | — | — | TORQUE TEAM BX56 | — | 400 | — | — | — |
| 065-00164-000 | — | — | 2X13X1400 | — | 400 | — | — | — |
| 065-00164-001 | — | — | 2X13X1400 | — | 400 | — | — | — |
| 065-00165-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00167-000 | — | — | 2X13X1325 | — | 400 | — | — | — |
| 065-00168-000 | — | — | — | — | — | — | — | — |
| 065-00170-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00170-001 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00172-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00172-001 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00173-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00174-000 | — | — | TORQUE TEAM 2/BX91 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00176-000 | — | — | TORQUE TEAM 2/BX81 | — | 590 | TORQUE FLEX 2/AX42 | — | 250 |
| 065-00176-000 | — | — | TORQUE TEAM 2/BX81 | — | 590 | TORQUE FLEX 2/AX42 | — | 250 |
| 065-00176-001 | — | — | TORQUE TEAM 2/BX78 | — | 590 | TORQUE FLEX 2/AX42 | — | 250 |
| 065-00177-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00184-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00184-001 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|-----|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00184-002 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00185-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX60 | — | 80 |
| 065-00189-000 | — | — | 2X13X1400 | — | 400 | — | — | — |
| 065-00190-000 | — | — | 2X13X1550 | — | 400 | — | — | — |
| 065-00191-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00193-000 | — | — | TORQUE TEAM 2/AX62 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00194-000 | — | — | 2X13X1550 | — | 400 | — | — | — |
| 065-00195-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00196-000 | — | — | TORQUE TEAM 2/AX62 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00198-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00199-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00200-000 | — | — | TORQUE TEAM 2/BX80 | — | 400 | 2X13X1625 | — | 80 |
| 065-00201-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1625 | — | 80 |
| 065-00202-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00202-001 | — | — | TORQUE TEAM 2/BX81 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00203-000 | — | — | 2X13X1375 | — | 400 | — | — | — |
| 065-00205-000 | — | — | TORQUE TEAM 2/BX84 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00205-001 | — | — | TORQUE TEAM 2/BX84 | — | 590 | 13AV1070 | — | 250 |
| 065-00208-000 | — | — | TORQUE TEAM 2/BX80 | — | 400 | 2X13X1625 | — | 80 |
| 065-00209-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1625 | — | 80 |
| 065-00211-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | 2X13X1625 | — | 80 |
| 065-00212-000 | — | — | TORQUE TEAM 2/BX76 | — | 400 | — | — | — |
| 065-00216-000 | — | — | TORQUE TEAM 2/BX89 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00216-001 | — | — | TORQUE TEAM 2/BX91 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00222-000 | — | — | 2X13X1625 | — | 400 | POLY V 6PK 1105 | — | 400 |
| 065-00225-000 | — | — | POLY V 6PK 1125 | — | 600 | — | — | — |
| 065-00232-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00232-001 | — | — | TORQUE TEAM 2/AX41 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00232-002 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00233-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00236-000 | — | — | TORQUE TEAM 2/BX91 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00237-000 | — | — | TORQUE TEAM 2/BX89 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|-----|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00238-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 2X13X1625 | — | — |
| 065-00240-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00241-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00242-000 | — | — | TORQUE TEAM 2/BX91 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00243-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00244-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | 2X13X1550 | — | 80 |
| 065-00245-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00246-000 | — | — | TORQUE TEAM 2/BX91 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00247-000 | — | — | TORQUE TEAM 2/BX89 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00251-000 | — | — | — | — | — | — | — | — |
| 065-00253-000 | — | — | TORQUE TEAM 2/BX77 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00254-002 | — | — | TORQUE TEAM 2/BX90 | — | 400 | — | — | — |
| 065-00255-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00256-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00257-000 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1750 | — | 400 |
| 065-00257-001 | — | — | 2X13X1550 | — | 400 | — | — | — |
| 065-00258-000 | — | — | 2X13X1625 | — | 400 | 13AV1025 | — | — |
| 065-00259-000 | — | — | TORQUE TEAM 2/BX76 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00260-000 | — | — | POLY V 6PK 1395 | — | 400 | POLY V 6PK 1275 | — | 400 |
| 065-00260-001 | — | — | POLY V 6PK 1395 | — | 400 | — | — | — |
| 065-00261-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 2X13X1625 | — | — |
| 065-00262-000 | — | — | POLY V 6PK 2345 | — | 600 | — | — | — |
| 065-00265-000 | — | — | POLY V 8PK 1795 | — | 400 | — | — | — |
| 065-00265-001 | — | — | POLY V 8PK 1795 | — | 400 | — | — | — |
| 065-00269-000 | — | — | TORQUE TEAM 2/BX84 | — | 400 | — | — | — |
| 065-00269-001 | — | — | TORQUE TEAM 2/BX87 | — | 400 | — | — | — |
| 065-00270-000 | — | — | POLY V 4PK 860 | — | 600 | — | — | — |
| 065-00272-000 | — | — | 2X13X1550 | — | 450 | POLY V 6PK 1800 | — | 400 |
| 065-00273-000 | — | — | TORQUE TEAM 2/AX64 | — | 400 | POLY V 6PK 1200 | — | 80 |
| 065-00274-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00274-001 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00275-000 | — | — | 2X13X1625 | — | 400 | POLY V 6PK 1200 | — | 80 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00277-000 | — | — | POLY V 6PK 1375 | — | 400 | — | — | — |
| 065-00278-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 2225 | — | 400 |
| 065-00282-000 | — | — | TORQUE TEAM 2/BX85 | — | 590 | TORQUE TEAM 2/AX40 | — | 250 |
| 065-00282-001 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX44 | — | 80 |
| 065-00283-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1625 | — | 80 |
| 065-00283-001 | — | — | TORQUE TEAM 2/BX86 | — | 400 | 2X13X1550 | — | 80 |
| 065-00283-002 | 102.657 | — | TORQUE TEAM B91 | — | — | 2X13X1400 | — | — |
| 065-00283-003 | 102.798 | — | TORQUE TEAM B90 | — | 595/630 | TORQUE TEAM A60 | — | 289/306 |
| 065-00283-006 | 104.138 | — | TORQUE TEAM B89 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00285-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2AX62 | — | 80 |
| 065-00286-000 | — | — | TORQUE TEAM BX56 | — | 400 | TORQUE TEAM 2AX42 | — | 80 |
| 065-00286-001 | — | — | TORQUE TEAM BX56 | — | 400 | — | — | — |
| 065-00288-000 | — | — | TORQUE TEAM 2/AX64 | — | 400 | POLY V 6PK 1105 | — | 400 |
| 065-00293-000 | — | — | POLY V 8PK 2315 | — | 500 | — | — | — |
| 065-00295-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00297-000 | — | — | TORQUE TEAM 2/BX90 | — | 400 | — | — | — |
| 065-00300-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00301-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | 13AV1090 | — | 80 |
| 065-00302-000 | — | — | TORQUE TEAM 2BX/83 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00303-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2AX60 | — | 80 |
| 065-00304-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00305-000 | — | — | 2X13X1625 | — | 400 | POLY V 8PK 955 | — | 400 |
| 065-00306-000 | — | — | TORQUE TEAM 2/BX92 | — | 400 | — | — | — |
| 065-00309-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00312-000 | — | — | TORQUE TEAM 2/BX48 | — | 400 | POLY V 5PK 1025 | — | 600 |
| 065-00316-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00317-000 | — | — | POLY V 6PK 1625 | — | 450 | POLY V 4PK 860 | — | 80 |
| 065-00318-000 | — | — | POLY V 6PK 1625 | — | 450 | POLY V 4PK 860 | — | 80 |
| 065-00319-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00320-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 955 | — | 400 |
| 065-00321-000 | — | — | 2X13X1625 | — | 400 | POLY V 8PK 955 | — | 400 |
| 065-00322-000 | — | — | TORQUE TEAM 2/AX62 | — | 400 | POLY V 8PK 1900 | — | 400 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|-----|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00323-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 955 | — | 400 |
| 065-00324-000 | — | — | TORQUE TEAM 2/AX62 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00326-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX44 | — | 80 |
| 065-00327-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | 13AV975 | — | 80 |
| 065-00329-000 | — | — | TORQUE TEAM 2/BX80 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00330-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00331-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2AX41 | — | 80 |
| 065-00332-000 | — | — | 2X13X1500 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00333-000 | — | — | 2X13X1550 | — | 400 | POLY V 6PK 1105 | — | 400 |
| 065-00334-000 | — | — | TORQUE TEAM 2/BX92 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00335-000 | — | — | TORQUE TEAM 2/BX92 | — | 400 | TORQUE TEAM 2/AX40 | — | 80 |
| 065-00336-000 | — | — | TORQUE TEAM 2/BX69 | — | 400 | TORQUE TEAM 2AX42 | — | 80 |
| 065-00338-000 | — | — | TORQUE TEAM 2/BX84 | — | 450 | TORQUE TEAM AX36 | — | 80 |
| 065-00338-003 | — | — | — | — | — | — | — | — |
| 065-00339-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1625 | — | 80 |
| 065-00340-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | 2X13X1550 | — | 80 |
| 065-00341-000 | — | — | TORQUE TEAM 2BX80 | — | 400 | 2X13X1550 | — | 80 |
| 065-00342-000 | — | — | 2X13X1425 | — | 400 | — | — | — |
| 065-00343-000 | — | — | TORQUE TEAM 2/BX62 | — | 400 | — | — | — |
| 065-00343-001 | — | — | TORQUE TEAM 2/BX62 | — | 400 | — | — | — |
| 065-00344-000 | — | — | TORQUE TEAM 2/BX97 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00345-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | — | — | — |
| 065-00346-000 | — | — | POLY V 6PK 1395 | — | 400 | POLY V 6PK 1275 | — | 400 |
| 065-00347-000 | — | — | POLY V 6PK 1395 | — | 400 | — | — | — |
| 065-00348-000 | — | — | TORQUE TEAM 2/BX97 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00349-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | — | — | — |
| 065-00351-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00352-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00353-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00354-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX44 | — | 80 |
| 065-00355-000 | — | — | TORQUE TEAM 2/BX89 | — | 400 | TORQUE TEAM 2/AX44 | — | 80 |
| 065-00356-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|-----------------------------|--------|-----|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00357-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00358-000 | — | — | TORQUE TEAM 2/BX85 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00359-000 | — | — | TORQUE TEAM 2/BX83 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00361-000 | — | — | TORQUE TEAM 2/BX83 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00362-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00363-000 | — | — | TORQUE TEAM 2/BX83 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00364-000 | — | — | TORQUE TEAM 2/BX80 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00365-000 | — | — | TORQUE TEAM 2BX/86 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00366-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | — | — | — |
| 065-00367-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2/AX40 | — | 80 |
| 065-00368-000 | — | — | TORQUE TEAM AX58 | — | 400 | — | — | — |
| 065-00369-000 | — | — | TORQUE TEAM AX58 | — | 400 | — | — | — |
| 065-00370-000 | — | — | TORQUE TEAM 2/BX46 AND 2/BX | — | 400 | TORQUE TEAM 2/AX60 | — | 80 |
| 065-00371-000 | — | — | TORQUE TEAM 2AX60 | — | 400 | POLY V 4PK 778 | — | 400 |
| 065-00372-000 | — | — | TORQUE TEAM AX69 | — | 400 | — | — | — |
| 065-00373-000 | — | — | TORQUE TEAM AX69 | — | 400 | — | — | — |
| 065-00374-000 | — | — | TORQUE TEAM 2/BX62 | 43,5 | 397 | POLY "V" 8PK 1900 | 42,5 | 808 |
| 065-00374-001 | — | — | 2X13AVX1550 | 43,5 | 397 | POLY "V" 8PK 1900 | 42,5 | 808 |
| 065-00375-000 | — | — | 2X13X1450 | — | 400 | POLY V 6PK 1750 | — | 400 |
| 065-00376-000 | — | — | 2X13X1425 | — | 400 | — | — | — |
| 065-00377-000 | — | — | 2X13X1550 | — | 400 | POLY V 8PK 1900 | — | 400 |
| 065-00378-000 | — | — | TORQUE TEAM BX45 AND 2/BX6 | — | 400 | TORQUE TEAM 2/AX38 | — | 70 |
| 065-00379-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00380-000 | — | — | TORQUE TEAM 2/BX86 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00381-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX42 | — | 80 |
| 065-00382-000 | — | — | TORQUE TEAM 2/BX88 | — | 400 | TORQUE TEAM 2/AX41 | — | 80 |
| 065-00385-000 | — | — | TORQUE TEAM 2AX/60 | — | 400 | — | — | — |
| 065-00387-000 | — | — | TORQUE TEAM 2/BX87 | — | 400 | TORQUE TEAM 2AX38 | — | 80 |
| 065-00389-000 | — | — | TORQUE TEAM 2/BX88 | — | 590 | TORQUE TEAM 2/AX40 | — | 250 |
| 065-00391-000 | — | — | 2X13X1625 | 43,5 | 397 | — | — | — |
| 065-00394-000 | — | — | TORQUE TEAM 13AV1070 | — | 400 | TORQUE TEAM 2/BX62 | — | 400 |
| 065-00394-001 | — | — | TORQUE TEAM 13AV1070 | 28 | 833 | TORQUE TEAM 2/BX62 | 47 | 413 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00394-002 | — | — | TORQUE TEAM 2/BX48 | — | 769 | 13AV1070 | 118 | 246 |
| 065-00396-000 | — | — | 2X13X1550 | — | — | — | — | — |
| 065-00397-000 | — | — | TORQUE TEAM 2/BX100 | 22 | 600 | 13AV1150 | 66 | 124 |
| 065-00397-002 | — | — | TORQUE TEAM 2/BX100 | 22 | 600 | 13AV1100 | 66 | 124 |
| 065-00397-003 | — | — | TORQUE TEAM 2/BX100 | 24 | 574 | 13AV1070 | 78 | 284 |
| 065-00397-004 | — | — | TORQUE TEAM 2/BX98 | 22 | 600 | 13AV1100 | 66 | 124 |
| 065-00398-000 | — | — | TORQUE TEAM 2/BX93 | — | 400 | 13AV1070 | — | 80 |
| 065-00399-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | — | — | — |
| 065-00400-000 | — | — | TORQUE TEAM 2/BX85 | 35 | 1255 | 13AV965 | 145 | 227 |
| 065-00401-000 | — | — | TORQUE TEAM 2/BX88 | — | — | 13AV1150 | — | — |
| 065-00401-001 | — | — | TORQUE TEAM 2/BX88 | — | 590 | 13AV1150 | — | 250 |
| 065-00401-004 | — | — | TORQUE TEAM 2/BX89 | 36 | 1312 | 13AV1150 | 92 | 219 |
| 065-00401-006 | — | — | TORQUE TEAM 2/BX89 | 30 | 911 | 13AV1150 | 75 | 145 |
| 065-00401-007 | — | — | TORQUE TEAM 2/BX88 | 30 | 911 | 13AV1138 | 75 | 145 |
| 065-00401-008 | — | — | TORQUE TEAM 2/BX89 | 28 | 653 | — | — | — |
| 065-00401-009 | — | — | TORQUE TEAM 2/BX87 | 26 | 719 | 13AV1070 | 75 | 145 |
| 065-00401-010 | — | — | TORQUE TEAM 2/BX84 | 27 | 719 | 13AV1045 | 75 | 145 |
| 065-00401-011 | — | — | TORQUE TEAM 2/BX89 | 28 | 653 | 13AV1045 | 75 | 145 |
| 065-00401-012 | — | — | TORQUE TEAM 2/BX87 | 26 | 719 | 13AV1070 | 75 | 145 |
| 065-00401-013 | — | — | TORQUE TEAM 2/BX87 | 26 | 719 | — | — | — |
| 065-00401-014 | 104.105 | — | TORQUE TEAM B91 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00403-000 | — | — | POLY "V" 8PK 1805 | — | 800 | — | — | — |
| 065-00404-000 | — | — | POLY "V" 8PK 1780 | — | 800 | — | — | — |
| 065-00405-000 | — | — | POLY "V" 8PK 1750 | — | 800 | — | — | — |
| 065-00406-000 | — | — | POLY "V" 8PK 2590 | — | AUT. | — | — | — |
| 065-00407-000 | — | — | TORQUE TEAM 2/AX55 | — | — | — | — | — |
| 065-00408-000 | — | — | POLY "V" 8PK 1805 | — | — | — | — | — |
| 065-00412-000 | — | — | POLY "V" 8PK 2590 | — | — | — | — | — |
| 065-00413-000 | — | — | TORQUE TEAM 2/BX83 | — | 450 | 2X13X1625 | — | 180 |
| 065-00414-000 | — | — | TORQUE TEAM 2/BX86 | 33 | 993 | 13AV1070 | 118 | 150 |
| 065-00415-000 | — | — | TORQUE TEAM 2/BX82 | — | — | 2X13X1625 | — | 260 |
| 065-00416-000 | — | — | TORQUE TEAM BX35 | — | — | TORQUE TEAM AX54 | — | — |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00417-000 | — | — | TORQUE TEAM 2/SPB2720 | — | 400 | 13AV1070 | — | 80 |
| 065-00419-000 | — | — | POLY "V" 8PK 1345 | — | — | — | — | — |
| 065-00420-000 | — | — | TORQUE TEAM 2/BX89 | — | 590 | 13AV1070 | — | 250 |
| 065-00421-000 | — | — | TORQUE TEAM 2/BX94 | — | 590 | 13AV1150 | — | 250 |
| 065-00422-000 | — | — | TORQUE TEAM 2/BX83 | 32 | 925 | 13AV1150 | 75 | 145 |
| 065-00422-001 | — | — | TORQUE TEAM 2/BX84 | 32 | 925 | 13AV1150 | 75 | 145 |
| 065-00422-002 | 104.149 | — | TORQUE TEAM B84 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00422-003 | — | — | TORQUE TEAM 2/BX81 | 32 | 925 | 13AV1175 | 75 | 145 |
| 065-00422-004 | — | — | TORQUE TEAM 2/BX84 | 32 | 925 | 13AV1150 | — | — |
| 065-00422-005 | — | — | TORQUE TEAM 2/BX81 | 32 | 925 | 13AV1070 | 90 | 153 |
| 065-00422-006 | — | — | TORQUE TEAM 2/BX81 | 32 | 925 | 13AV1070 | 90 | 153 |
| 065-00422-007 | — | — | TORQUE TEAM 2/BX84 | 32 | 925 | 13AV1045 | 75 | 209 |
| 065-00422-008 | — | — | TORQUE TEAM 2/BX84 | 32 | 925 | 13AV1045 | 75 | 209 |
| 065-00422-009 | — | — | TORQUE TEAM 2/BX80 | 32 | 925 | 13AV1150 | — | — |
| 065-00422-010 | — | — | TORQUE TEAM 2/BX84 | 32 | 925 | — | — | — |
| 065-00422-011 | — | — | TORQUE TEAM 2/BX81 | 32 | 925 | 13AV1070 | 90 | 153 |
| 065-00422-012 | — | — | TORQUE TEAM 2/BX78 | 32 | 925 | 13AV1175 | 76 | 260 |
| 065-00422-013 | — | — | TORQUE TEAM 2/BX78 | 31 | 718 | 13AV1120 | 76 | 260 |
| 065-00422-015 | 104.326 | — | TORQUE TEAM B80 | — | 561/594 | 13AV1060 | — | 244/258 |
| 065-00422-016 | 104.350 | — | TORQUE TEAM B85 | — | 561/594 | 13AV1120 | — | 287/304 |
| 065-00423-000 | — | — | POLY "V" 6PK 1150 | — | 190 | — | — | — |
| 065-00424-000 | — | — | POLY "V" 8PK 1805 | — | 800 | — | — | — |
| 065-00424-003 | — | — | — | — | — | — | — | — |
| 065-00428-000 | — | — | TORQUE TEAM 2/BX86 | — | 450 | 13AV965 | — | 180 |
| 065-00429-000 | — | — | TORQUE TEAM 2/BX84 | — | 450 | 13AV965 | — | 180 |
| 065-00430-000 | — | — | TORQUE TEAM 2/BX84 | — | 590 | 13AV1150 | — | 250 |
| 065-00432-000 | — | — | TORQUE TEAM 2/AX68 | 45,5 | 455 | POLY "V" 8PK 2390 | — | — |
| 065-00432-000 | 103.702 | — | POLY-V 6PK1960 | — | — | — | — | — |
| 065-00432-001 | 104.072 | — | POLY-V 6PK1960 | — | — | — | — | — |
| 065-00432-002 | 104.230 | — | POLY-V 6PK2140 | — | — | — | — | — |
| 065-00432-003 | 104.321 | — | POLY-V 6PK1545 | — | — | — | — | — |
| 065-00433-000 | — | — | TORQUE TEAM 2/BX61 | — | — | — | — | — |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|---------------------------|--------|------|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00435-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | TORQUE FLEX BX/43 | — | 400 |
| 065-00436-000 | — | — | TORQUE TEAM 2/BX86 | — | 450 | 13AV965 | — | 180 |
| 065-00437-001 | — | — | 2X13X1325 | — | 400 | POLY "V" 8PK 1780 | — | — |
| 065-00437-002 | — | — | 2X13X1325 | 94 | 821 | POLY "V" 8PK 1780 | 77 | 551 |
| 065-00437-003 | — | — | 2X13X1325 | 94 | 821 | — | — | — |
| 065-00437-004 | — | — | — | — | — | — | — | — |
| 065-00437-005 | — | — | 2X13X1325 | 94 | 821 | POLY "V" 8PK 1780 | 77 | 551 |
| 065-00437-006 | — | — | 2X13X1325 | 94 | 821 | — | — | — |
| 065-00437-007 | — | — | — | — | — | — | — | — |
| 065-00438-000 | — | — | TORQUE TEAM 2/BX82 | — | 450 | 2X13X1625 | — | 180 |
| 065-00439-000 | — | — | 2X13AVX1750 | 45,5 | 569 | POLY "V" 8PK 2390 | — | — |
| 065-00439-001 | 103.696 | — | POLY-V 6PK1920 | — | — | — | — | — |
| 065-00440-000 | — | — | TORQUE TEAM 2/AX64 | 55,7 | 1388 | — | — | — |
| 065-00441-000 | — | — | TORQUE TEAM 2/BX85 | — | 450 | 13AV965 | — | 180 |
| 065-00443-000 | — | — | TORQUE TEAM 2/BX84 | — | 450 | 13AV965 | — | 180 |
| 065-00444-001 | — | — | 2X13AVX1300 | — | 400 | POLY "V" 8PK 1780 | — | — |
| 065-00444-002 | — | — | 2X13AVX1300 | 82 | 596 | POLY "V" 8PK 1780 | 67 | 398 |
| 065-00444-003 | — | — | 2X13AVX1300 | 82 | 596 | — | — | — |
| 065-00444-004 | — | — | 2X13AVX1300 | 82 | 596 | POLY "V" 8PK 1780 | 67 | 398 |
| 065-00444-005 | — | — | 2X13AVX1300 | 82 | 596 | — | — | — |
| 065-00445-000 | — | — | TORQUE TEAM 2/BX94 | — | 590 | 13AV1175 | — | 250 |
| 065-00447-000 | — | — | 2X13X1625 | — | — | TORQUE TEAM 2/BX86 | — | — |
| 065-00448-000 | — | — | TORQUE TEAM 2/AX64 | 45,5 | 926 | POLY "V" 8PK 2390 | — | — |
| 065-00450-000 | — | — | TORQUE TEAM BX41 - 2/BX63 | — | 400 | 2X13X1625 | — | 180 |
| 065-00451-000 | — | — | — | — | — | — | — | — |
| 065-00455-000 | — | — | TORQUE TEAM BX64 | — | 400 | POLY "V" 8PK 1815 | — | — |
| 065-00456-000 | — | — | TORQUE TEAM 2/BX85 | — | 450 | 13AV965 | — | 180 |
| 065-00457-000 | — | — | TORQUE TEAM 2/BX86 | — | 450 | 2X13X1625 | — | 180 |
| 065-00459-001 | 104.042 | — | 2X13X1325 | — | — | — | — | — |
| 065-00460-000 | — | — | TORQUE TEAM 2/BX88 | — | 590 | 13AV1150 | — | 250 |
| 065-00461-000 | — | — | TORQUE TEAM BX50 | — | 400 | 13AV1150 | — | 80 |
| 065-00462-000 | — | — | TORQUE TEAM 2/BX86 | 31 | — | 13AV965 | 74 | — |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00464-000 | — | — | TORQUE FLEX BX54 | 77 | 791 | — | — | — |
| 065-00464-001 | — | — | — | — | — | — | — | — |
| 065-00464-002 | — | — | TORQUE FLEX BX54 | — | 400 | — | — | — |
| 065-00464-003 | — | — | TORQUE FLEX BX54 | 77 | 791 | — | — | — |
| 065-00465-000 | — | — | TORQUE TEAM 2/BX94 | — | 590 | 13AV1150 | — | 250 |
| 065-00465-001 | — | — | TORQUE TEAM 2/BX94 | 25 | 541 | 13AV1150 | 69 | 127 |
| 065-00465-002 | 104.339 | — | TORQUE TEAM B93 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00466-000 | — | — | TORQUE TEAM 2/BX88 | — | 590 | 13AV1150 | — | 250 |
| 065-00467-000 | — | — | TORQUE TEAM 2/BX80 | 32 | 925 | 13AV1150 | 75 | 145 |
| 065-00467-002 | — | — | — | — | — | — | — | — |
| 065-00467-003 | — | — | TORQUE TEAM 2/BX80 | 32 | 925 | 13AV1070 | 90 | 153 |
| 065-00468-000 | — | — | TORQUE TEAM 2/BX85 | — | 450 | 13AV965 | — | 180 |
| 065-00469-000 | — | — | TORQUE TEAM 2/BX93 | — | 590 | 13AV1070 | — | 250 |
| 065-00470-000 | — | — | TORQUE TEAM 2/BX81 | 32 | 925 | 13AV1150 | 75 | 145 |
| 065-00470-002 | — | — | TORQUE TEAM 2/BX81 | 27 | 527 | 13AV1070 | 118 | 212 |
| 065-00470-003 | — | — | TORQUE TEAM 2/BX83 | 29 | 610 | 13AV1070 | 118 | 212 |
| 065-00470-004 | — | — | TORQUE TEAM 2/BX83 | 29 | 610 | 13AV1070 | 118 | 212 |
| 065-00472-000 | — | — | TORQUE TEAM 2/BX86 | 29 | 908 | 13AV965 | 118 | 150 |
| 065-00472-001 | — | — | TORQUE TEAM 2/BX87 | 29 | 908 | 13AV965 | 118 | 150 |
| 065-00473-000 | — | — | TORQUE TEAM 2/BX86 | — | 450 | 2X13X1625 | — | 180 |
| 065-00474-000 | — | — | TORQUE TEAM 2/BX86 | — | 590 | 13AV1070 | — | 250 |
| 065-00475-000 | — | — | — | — | — | — | — | — |
| 065-00476-000 | — | — | TORQUE TEAM 2/BX87 | — | 450 | 2X13X1625 | — | 180 |
| 065-00477-000 | — | — | TORQUE TEAM 2/BX89 | — | 590 | 13AV1070 | — | 250 |
| 065-00478-000 | — | — | TORQUE TEAM 2/BX100 | — | 590 | 13AV1150 | — | 250 |
| 065-00479-000 | — | — | — | — | — | — | — | — |
| 065-00480-000 | — | — | TORQUE TEAM 2/BX90 | — | 450 | 2X13X1625 | — | 180 |
| 065-00481-000 | — | — | TORQUE TEAM 2/BX81 | — | 400 | 13AV1150 | — | — |
| 065-00482-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 13AV965 | — | — |
| 065-00482-001 | — | — | TORQUE TEAM 2/BX87 | 30 | 900 | 13AV965 | 118 | 150 |
| 065-00482-002 | — | — | TORQUE TEAM 2/BX85 | 30 | 900 | 13AV965 | 118 | 150 |
| 065-00482-003 | — | — | TORQUE TEAM 2/BX83 | 30 | 900 | 13AV965 | 118 | 150 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|------|-------------------------------|--------|-----|
| | | | | HZ | N | | HZ | N |
| 065-00500-000 | — | — | — | — | — | — | — | — |
| 065-00501-000 | — | — | — | — | — | — | — | — |
| 065-00503-000 | — | — | TORQUE TEAM 2/BX89 | — | 590 | 13AV1070 | — | 250 |
| 065-00503-001 | — | — | TORQUE TEAM 2/BX89 | 27 | 864 | 13AV1050 | 75 | 145 |
| 065-00504-000 | — | — | TORQUE TEAM 2/BX85 | 33 | 993 | 13AV965 | 118 | 150 |
| 065-00505-000 | — | — | — | — | — | — | — | — |
| 065-00506-000 | — | — | — | — | — | — | — | — |
| 065-00507-000 | — | — | — | — | — | — | — | — |
| 065-00508-000 | — | — | — | — | — | — | — | — |
| 065-00510-000 | — | — | TORQUE TEAM 2/BX89 | 27 | 864 | 13AV965 | 118 | 150 |
| 065-00510-001 | — | — | TORQUE TEAM 2/BX89 | 27 | 864 | 13AV1150 | 75 | 145 |
| 065-00511-000 | — | — | POLY "V" 9PK 2340 | — | — | — | — | — |
| 065-00511-001 | — | — | POLY "V" 9PK 2340 | — | — | — | — | — |
| 065-00512-000 | — | — | TORQUE TEAM 2/BX84 | 33 | 993 | 13AV965 | 118 | 150 |
| 065-00513-000 | — | — | TORQUE TEAM 2/BX85 | — | — | — | — | — |
| 065-00515-000 | — | — | — | — | — | — | — | — |
| 065-00515-000 | 103.688 | — | POLY-V 6PK1545 | — | — | — | — | — |
| 065-00515-001 | — | — | POLY "V" 9PK 2110 | 118 | 360 | — | — | — |
| 065-00516-000 | — | — | TORQUE TEAM 2/BX87 | 33 | 1047 | — | — | — |
| 065-00517-000 | — | — | TORQUE TEAM BX47 | — | 400 | — | — | — |
| 065-00518-000 | — | — | TORQUE TEAM 2/BX84 | — | 450 | 2X13X1625 | — | 180 |
| 065-00519-000 | — | — | TORQUE TEAM 2/BX73 | — | 590 | 13AV1175 | — | 250 |
| 065-00519-001 | — | — | TORQUE TEAM 2/BX80 | 28 | 762 | 13AV1045 | 118 | 274 |
| 065-00519-002 | — | — | TORQUE TEAM 2/BX76 | 26 | 688 | 13AV1070 | 118 | 274 |
| 065-00520-000 | — | — | TORQUE TEAM BX74 | — | 450 | — | — | — |
| 065-00522-000 | — | — | TORQUE FLEX BX46 | — | 280 | 13AV990 | — | 250 |
| 065-00523-000 | — | — | TORQUE TEAM 2/BX86 | 30 | 900 | 13AV965 | 118 | 150 |
| 065-00524-000 | — | — | TORQUE TEAM 2/BX86 | 30 | 900 | — | — | — |
| 065-00525-000 | — | — | TORQUE TEAM 2/BX88 | 33 | 1155 | — | — | — |
| 065-00526-000 | — | — | TORQUE TEAM 2/BX88 | 33 | 1155 | 13AV1175 | 67 | 148 |
| 065-00526-001 | — | — | TORQUE TEAM 2/BX88 | 33 | 1155 | — | — | — |
| 065-00527-000 | — | — | TORQUE TEAM 2/BX88 | 33 | 1155 | — | — | — |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00528-000 | — | — | 2X13AVX2175 | — | 400 | POLY "V" 6PK 1355 | — | 800 |
| 065-00529-000 | — | — | TORQUE TEAM 2/BX90/ TORQUE FLE | — | 450/590 | 13AV990 | — | 250 |
| 065-00530-000 | — | — | TORQUE TEAM 2/BX88 | 33 | 1155 | 13AV965 | 118 | 150 |
| 065-00530-002 | 104.348 | — | TORQUE TEAM B88 | — | 561/594 | 13AV1135 | — | 287/304 |
| 065-00530-003 | 104.360 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00531-000 | — | — | — | — | — | — | — | — |
| 065-00532-000 | — | — | — | — | — | — | — | — |
| 065-00533-000 | — | — | TORQUE TEAM 2/BX87 | 30 | 900 | 13AV1150 | 43 | 400 |
| 065-00534-000 | — | — | — | — | — | — | — | — |
| 065-00535-000 | — | — | — | — | — | — | — | — |
| 065-00536-000 | — | — | TORQUE TEAM 2/BX87 | 30 | 900 | — | — | — |
| 065-00537-000 | — | — | TORQUE TEAM 2/BX83 | 33 | 993 | — | — | — |
| 065-00538-000 | — | — | TORQUE TEAM 2/BX86 | 33 | 993 | 13AV975 | 118 | 150 |
| 065-00538-001 | — | — | TORQUE TEAM 2/BX84 | 28 | — | — | — | — |
| 065-00538-003 | — | — | TORQUE TEAM 2/BX89 | 28 | — | 13AV975 | 74 | — |
| 065-00538-004 | 104.319 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00539-000 | — | — | TORQUE TEAM 2/BX83 | 30 | 881 | 2X13X1625 | 43 | 400 |
| 065-00540-000 | — | — | TORQUE TEAM 2/BX87 | 30 | 911 | 13AV1150 | 75 | 145 |
| 065-00541-000 | — | — | TORQUE TEAM 2/BX85 | 29 | 861 | 2X13X1625 | 42 | 411 |
| 065-00542-000 | — | — | TORQUE TEAM 2/BX90 | — | 480 | 2X13X1625 | — | 450 |
| 065-00543-000 | — | — | TORQUE TEAM 2/BX70 | 32 | 621 | 13AV1090 | 63 | 104 |
| 065-00543-002 | — | — | — | — | — | — | — | — |
| 065-00543-004 | — | — | TORQUE TEAM 2/BX70 | 32 | 708 | 13AV1090 | 63 | 104 |
| 065-00544-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 13AV965 | — | — |
| 065-00544-001 | — | — | TORQUE TEAM 2/BX88 | 30 | 900 | 13AV965 | 145 | 227 |
| 065-00544-002 | — | — | TORQUE TEAM 2/BX85 | 30 | 900 | 13AV965 | 145 | 227 |
| 065-00545-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 13AV965 | — | — |
| 065-00545-001 | — | — | TORQUE TEAM 2/BX87 | 29 | 908 | 13AV965 | 118 | 150 |
| 065-00546-000 | — | — | — | — | — | — | — | — |
| 065-00547-000 | — | — | — | — | — | — | — | — |
| 065-00548-000 | — | — | TORQUE TEAM 2/BX86 | 29 | 908 | 2X13X1625 | 42 | 411 |
| 065-00548-000 | 103.625 | — | TORQUE TEAM B88 | — | — | TORQUE TEAM A60 | — | — |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00550-000 | 103.835 | — | TORQUE TEAM B88 | — | — | 13AV1135 | — | — |
| 065-00550-001 | 103.116 | — | TORQUE TEAM B88 | — | 561/594 | 13AV1120 | — | 287/304 |
| 065-00551-001 | 102.941 | — | TORQUE TEAM B83 | — | — | 13AV1135 | — | — |
| 065-00551-002 | 104.324 | — | TORQUE TEAM B82 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00552-000 | 102.489 | — | TORQUE TEAM B85 | — | — | 13AV1525 | — | — |
| 065-00552-001 | 103.966 | — | TORQUE TEAM B84 | — | 595/630 | TORQUE TEAM A60 | — | 240/254 |
| 065-00552-002 | 104.048 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00552-003 | 104.051 | — | TORQUE TEAM B84 | — | 595/630 | TORQUE TEAM A60 | — | 240/255 |
| 065-00552-004 | 104.084 | — | TORQUE TEAM B83 | — | 595/630 | TORQUE TEAM A60 | — | 240/254 |
| 065-00552-005 | 104.087 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00553-000 | — | — | TORQUE TEAM 2/BX86 | — | — | 2X13X1625 | — | — |
| 065-00554-000 | — | — | TORQUE TEAM 2/BX86 | 30 | 900 | 2X13X1625 | 42 | 411 |
| 065-00555-001 | 103.937 | — | TORQUE TEAM B96 | — | — | 13AV1060 | — | — |
| 065-00556-000 | — | — | TORQUE TEAM 2/BX83 | 33 | 932 | — | — | — |
| 065-00558-000 | — | — | 2X13X1325 | 50 | 401 | — | — | — |
| 065-00559-000 | — | — | TORQUE TEAM 2/AX60 | 52 | 382 | — | — | — |
| 065-00560-000 | — | — | 2X13X1600 | 55 | 587 | — | — | — |
| 065-00561-000 | — | — | 2X13X1570 | 50 | 401 | — | — | — |
| 065-00562-000 | — | — | TORQUE TEAM 2/BX93 | 31 | 1197 | 13AV1150 | 75 | 145 |
| 065-00564-000 | 102.807 | — | TORQUE TEAM B63 | — | — | 8PK1780 | — | — |
| 065-00564-001 | 104.249 | — | TORQUE TEAM B62 | — | — | 8PK1780 | — | — |
| 065-00565-000 | 103.727 | — | TORQUE TEAM B87 | — | — | 13AV1525 | — | — |
| 065-00566-000 | 102.411 | — | TORQUE TEAM B88 | — | — | 13AV1525 | — | — |
| 065-00566-001 | 102.853 | — | TORQUE TEAM B88 | — | — | 13AV1450 | — | — |
| 065-00566-002 | 103.624 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 240/255 |
| 065-00566-004 | 104.004 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00566-006 | 104.053 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00566-008 | 104.022 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00566-009 | 104.067 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 289/306 |
| 065-00568-001 | 103.999 | — | TORQUE TEAM B85 | — | 650 | 13AV1420 | — | 260 |
| 065-00570-000 | 102.437 | — | TORQUE TEAM B71/B41 | — | — | TORQUE TEAM A60 | — | — |
| 065-00570-002 | 104.089 | — | TORQUE TEAM B71/B38 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00570-003 | 104.116 | — | TORQUE TEAM B71/B40 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00570-004 | 104.403 | — | SPBX-1000-B38 | — | 360/380 | AVX13X1025 | — | 244/258 |
| 065-00571-000 | 102.687 | — | TORQUE TEAM B86 | — | — | TORQUE TEAM A60 | — | — |
| 065-00571-001 | 104.055 | — | TORQUE TEAM B83 | — | 403/427 | TORQUE TEAM A60 | — | 322/341 |
| 065-00572-000 | 103.083 | — | TORQUE TEAM B98 | — | — | 2X13X1525 | — | — |
| 065-00573-000 | 102.863 | — | TORQUE TEAM B80 | — | 650 | TORQUE TEAM A60 | — | 260 |
| 065-00573-002 | 103.979 | — | TORQUE TEAM B80 | — | 650 | 2X13X1450 | — | 260 |
| 065-00573-003 | 104.066 | — | TORQUE TEAM B81 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00573-004 | 104.065 | — | TORQUE TEAM B80 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00573-005 | 104.096 | — | TORQUE TEAM B80 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00573-006 | 104.161 | — | TORQUE TEAM B80 | — | 595/630 | 13AV1000 | — | 246/260 |
| 065-00574-000 | 102.727 | — | TORQUE TEAM B83 | — | 650 | TORQUE TEAM A60 | — | 260 |
| 065-00574-002 | 104.057 | — | TORQUE TEAM B83 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00574-003 | 104.060 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00574-005 | 104.061 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00574-007 | 104.060 | — | TORQUE TEAM B83 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00574-008 | 104.060 | — | TORQUE TEAM B83 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00575-004 | 104.085 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00576-000 | 103.059 | — | TORQUE TEAM B88 | — | — | 2X13X1450 | — | — |
| 065-00577-000 | 102.641 | — | TORQUE TEAM B85 | — | — | 2X13X1450 | — | — |
| 065-00581-000 | 102.909 | — | TORQUE TEAM B86 | — | — | 2X13X1450 | — | — |
| 065-00582-000 | 102.977 | — | TORQUE TEAM B86 | — | — | TORQUE TEAM A60 | — | — |
| 065-00582-001 | 104.136 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00583-000 | 103.683 | — | TORQUE TEAM B86 | — | 650 | 13AV0975 | — | 170 |
| 065-00584-000 | 103.337 | — | TORQUE TEAM B85 | — | — | TORQUE TEAM A41 | — | — |
| 065-00584-001 | 103.305 | — | TORQUE TEAM B83 | — | — | TORQUE TEAM A41 | — | — |
| 065-00584-002 | 104.248 | — | TORQUE TEAM B82 | — | 561/594 | 13AV1100 | — | 183/193 |
| 065-00584-004 | 104.371 | — | TORQUE TEAM B82 | — | 561/594 | 13AV1150 | — | 246/260 |
| 065-00585-000 | — | — | TORQUE TEAM 2/BX85 | 29 | 861 | 13AV965 | 118 | 150 |
| 065-00586-001 | 104.225 | — | TORQUE TEAM B91 | — | 561/594 | 13AV1020 | — | 246/260 |
| 065-00587-000 | 102.894 | — | TORQUE TEAM B87 | — | 561/594 | 13AV1120 | — | 244/258 |
| 065-00587-001 | 104.204 | — | TORQUE TEAM B90 | — | 561/594 | AVX13X1020 | — | 244/258 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00587-002 | 104.212 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00589-001 | 104.079 | — | TORQUE TEAM B87 | — | 561/594 | 13AV1100 | — | 196/208 |
| 065-00589-002 | 104.080 | — | TORQUE TEAM B90 | — | 561/594 | 13AV1060 | — | 244/258 |
| 065-00589-003 | 104.327 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1045 | — | 244/259 |
| 065-00589-004 | 102.884 | — | TORQUE TEAM B87 | — | 561/594 | AVX13x1050 | — | 287/304 |
| 065-00589-005 | 104.369 | — | TORQUE TEAM B90 | — | 561/594 | 13AV1120 | — | 287/304 |
| 065-00590-001 | 104.073 | — | TORQUE TEAM B87 | — | 595/630 | 13AV1000 A-38 | — | 244/258 |
| 065-00590-002 | 104.075 | — | TORQUE TEAM B89 | — | 595/630 | 13AV1500 | — | 322/341 |
| 065-00590-003 | 104.071 | — | TORQUE TEAM B88 | — | 595/630 | 13AV1000 | — | 246/260 |
| 065-00590-004 | 104.070 | — | TORQUE TEAM B88 | — | 595/630 | TORQUE TEAM A60 | — | 240/255 |
| 065-00590-005 | 104.137 | — | TORQUE TEAM B88 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00590-006 | 104.140 | — | TORQUE TEAM B89 | — | 595/630 | TORQUE TEAM A60 | — | 322/341 |
| 065-00592-000 | 103.900 | — | TORQUE TEAM B87 | — | 595/630 | 13AV0950 | — | 246/260 |
| 065-00592-001 | 103.914 | — | TORQUE TEAM B85 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00593-000 | — | — | TORQUE TEAM 2/BX85 | 33 | 1047 | — | — | — |
| 065-00593-001 | — | — | TORQUE TEAM 2/BX86 | 19,4 | 440 | — | — | — |
| 065-00593-004 | — | — | TORQUE TEAM 2/BX82 | 25 | 498 | 13AV1045 | 99 | 136 |
| 065-00594-002 | 104.309 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00595-000 | — | — | TORQUE TEAM 2/BX67 | 45,5 | 926 | — | — | — |
| 065-00597-000 | — | — | TORQUE TEAM 2/BX71 | 45,5 | 926 | — | — | — |
| 065-00598-000 | 103.049 | — | TORQUE TEAM B87 | — | — | 2X13X1525 | — | — |
| 065-00599-000 | 103.909 | — | TORQUE TEAM B83 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00599-001 | 103.908 | — | TORQUE TEAM B83 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00600-001 | 104.246 | — | TORQUE TEAM B100 | — | 595/630 | 13AV1150 | — | 246/260 |
| 065-00601-000 | 103.925 | — | TORQUE TEAM B89 | — | — | 13AV1135 | — | — |
| 065-00602-000 | — | — | TORQUE TEAM 2/BX94 | 25 | 854 | 13AV1150 | 75 | 145 |
| 065-00602-001 | — | — | TORQUE TEAM 2/BX94 | 25 | 854 | 13AV1150 | 75 | 145 |
| 065-00602-002 | — | — | TORQUE TEAM 2/BX94 | 25 | 827 | 13AV1150 | 75 | 145 |
| 065-00602-003 | — | — | TORQUE TEAM 2/BX94 | 25 | 854 | 13AV1150 | 75 | 145 |
| 065-00602-004 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |
| 065-00602-005 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |
| 065-00602-006 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00602-006 | 104.100 | — | TORQUE TEAM B94 | — | 561/594 | 13AV1020 | — | 183/194 |
| 065-00602-007 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |
| 065-00602-008 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |
| 065-00602-009 | — | — | TORQUE TEAM 2/BX95 | 25 | 827 | 13AV1045 | 75 | 209 |
| 065-00602-010 | — | — | TORQUE TEAM 2/BX94 | 25 | 827 | 13AV1150 | 75 | 145 |
| 065-00602-012 | — | — | TORQUE TEAM 2/BX92 | 26 | 544 | 13AV1045 | 75 | 209 |
| 065-00602-013 | 104.287 | — | TORQUE TEAM B96 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00602-014 | — | — | TORQUE TEAM 2/BX95 | 24 | 540 | 13AV1020 | 95 | 251 |
| 065-00602-015 | 104.100 | — | TORQUE TEAM B95 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00602-016 | 104.345 | — | TORQUE TEAM B94 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00603-000 | 103.817 | — | TORQUE TEAM B86 | — | — | TORQUE TEAM A60 | — | — |
| 065-00605-000 | — | — | TORQUE TEAM 2/BX78 | 32 | 925 | 2X13AVX1020 | 118 | 300 |
| 065-00605-001 | — | — | TORQUE TEAM 2/BX78 | 32 | 925 | 2X13AVX1020 | 118 | 300 |
| 065-00606-000 | 104.343 | — | TORQUE TEAM B85 | — | 561/594 | 13AV1100 | — | 287/304 |
| 065-00606-001 | 104.083 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1020 | — | 183/194 |
| 065-00607-000 | 103.714 | — | TORQUE TEAM B89 | — | 561/594 | — | — | — |
| 065-00609-002 | 104.020 | — | 2X13X1610 | — | — | — | — | — |
| 065-00610-000 | 103.959 | — | TORQUE TEAM B73 | — | 600 | — | — | — |
| 065-00610-001 | 103.955 | — | TORQUE TEAM B78 | — | 600 | 13AV1060 | — | 170 |
| 065-00612-000 | 103.867 | — | TORQUE TEAM B92 | — | — | 2X13X1450 | — | — |
| 065-00613-000 | — | — | TORQUE TEAM 2/BX82 | 30 | 911 | 13AV1175 | 75 | 145 |
| 065-00613-001 | — | — | TORQUE TEAM 2/BX84 | 30 | 911 | 13AV1175 | 75 | 145 |
| 065-00613-003 | — | — | TORQUE TEAM 2/BX87 | 30 | 911 | 13AV1175 | 75 | 145 |
| 065-00613-008 | — | — | TORQUE TEAM 2/BX87 | 30 | 911 | 13AV1175 | 75 | 145 |
| 065-00613-009 | — | — | — | — | — | — | — | — |
| 065-00613-010 | — | — | TORQUE TEAM 2/BX87 | 30 | 911 | 13AV1045 | 118 | 274 |
| 065-00613-011 | — | — | TORQUE TEAM 2/BX81 | 28 | 542 | 13AV1070 | 82 | 253 |
| 065-00615-000 | 103.965 | — | TORQUE TEAM B83 | — | 650 | 13AV1120 | — | 287/304 |
| 065-00615-002 | 104.049 | — | TORQUE TEAM B83 | — | 578/612 | 13AV1020 | — | 244/258 |
| 065-00615-003 | 103.816 | — | TORQUE TEAM B84 | — | 578/612 | TORQUE TEAM A60 | — | 244/258 |
| 065-00617-000 | — | — | TORQUE TEAM 2/BX86 | 30 | 768 | 13AV1045 | 118 | 274 |
| 065-00618-000 | — | — | TORQUE TEAM 2/BX101 | 25 | 854 | 13AV965 | 118 | 150 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00618-001 | — | — | — | — | — | — | — | — |
| 065-00618-002 | — | — | TORQUE TEAM 2/BX101 | 22 | 870 | 13AV1150 | 58 | 347 |
| 065-00618-003 | — | — | 2-XPB2794 - OPTIBELT | 22 | 870 | 13AV1045 | 58 | 347 |
| 065-00619-000 | — | — | — | — | — | TORQUE FLEX BX/42 | 44 | 150 |
| 065-00620-001 | — | — | TORQUE TEAM 2/BX83 | 32 | 894 | 13AV965 | 118 | 150 |
| 065-00620-002 | — | — | TORQUE TEAM 2/BX83 | 28 | 859 | TORQUE TEAM 2/AX62 | 42 | 350 |
| 065-00620-004 | — | — | TORQUE TEAM 2/BX81 | 28 | 859 | 2X13AVX1500 | 42 | 335 |
| 065-00620-006 | — | — | TORQUE TEAM 2/BX81 | 30 | 786 | 13AV1045 | 118 | 274 |
| 065-00620-007 | — | — | TORQUE TEAM 2/BX83 | 28 | 859 | 13AV990 | 118 | 150 |
| 065-00620-008 | — | — | TORQUE TEAM 2/BX81 | 32 | 894 | 2X13AVX1475 | 47 | 413 |
| 065-00620-009 | — | — | TORQUE TEAM 2/BX83 | 28 | 859 | TORQUE TEAM 2/AX62 | 47 | 413 |
| 065-00620-010 | — | — | TORQUE TEAM 2/BX81 | 31 | 610 | 13AV990 | 118 | 212 |
| 065-00620-011 | — | — | TORQUE TEAM 2/BX84 | 28 | 583 | 13AV965 | 118 | 212 |
| 065-00620-012 | — | — | TORQUE TEAM 2/BX84 | 28 | 583 | 13AV1020 | 118 | 212 |
| 065-00620-013 | — | — | TORQUE TEAM 2/BX84 | 28 | 583 | TORQUE TEAM 2/AX60 | 36 | 255 |
| 065-00620-014 | — | — | TORQUE TEAM 2/BX82 | 31 | 610 | 13AV1020 | 118 | 212 |
| 065-00620-015 | — | — | TORQUE TEAM 2/BX82 | 31 | 610 | TORQUE TEAM 2/AX59 | 37 | 255 |
| 065-00620-016 | — | — | TORQUE TEAM 2/BX80 | 27 | 555 | — | — | — |
| 065-00620-022 | 103.908 | — | TORQUE TEAM B83 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00620-023 | 104.216 | — | TORQUE TEAM B86 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00620-025 | 104.223 | — | TORQUE TEAM B87 | — | 595/630 | 13AV0950 | — | 244/258 |
| 065-00620-026 | 104.087 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00620-027 | 104.222 | — | TORQUE TEAM B87 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00620-028 | 104.048 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00620-029 | 104.221 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00620-030 | 104.363 | — | TORQUE TEAM B83 | — | 595/630 | 13AV1100 | — | 287/304 |
| 065-00620-031 | — | — | 2-XPB2100 - OPTIBELT | 31 | 610 | AVX13X1025 | 118 | 212 |
| 065-00620-032 | 104.385 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1100 | — | 287/304 |
| 065-00620-033 | — | 050-0921408-052 | 2-XPB2140 | — | 660 | AVX13 X1000 A 1025 | — | 290 |
| 065-00621-000 | — | — | TORQUE TEAM 2/BX81 | 28 | 656 | 2X13AVX1070 | 75 | 209 |
| 065-00621-001 | — | — | TORQUE TEAM 2/BX81 | 30 | 726 | 13AV1045 | 118 | 274 |
| 065-00621-002 | — | — | TORQUE TEAM 2/BX83 | 28 | 656 | 13AV990 | 150 | 118 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00621-003 | — | — | TORQUE TEAM 2/BX83 | 28 | 656 | TORQUE TEAM 2/AX62 | 42 | 350 |
| 065-00621-004 | — | — | TORQUE TEAM 2/BX81 | 28 | 656 | 2X13AVX1070 | 75 | 209 |
| 065-00621-005 | — | — | TORQUE TEAM 2/BX81 | 30 | 726 | 13AV990 | 118 | 212 |
| 065-00621-006 | — | — | TORQUE TEAM 2/BX81 | 28 | 656 | 2X13AVX1070 | 75 | 209 |
| 065-00621-007 | — | — | TORQUE TEAM 2/BX81 | 30 | 610 | 13AV1020 | 118 | 274 |
| 065-00621-007 | 104.284 | — | TORQUE TEAM B83 | — | 578/612 | 13AV1050 | — | 244/258 |
| 065-00621-008 | — | — | TORQUE TEAM 2/BX84 | 27 | 583 | 13AV1020 | 118 | 274 |
| 065-00621-010 | 104.217 | — | TORQUE TEAM B85 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00621-012 | 104.367 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1120 | — | 244/258 |
| 065-00621-013 | 104.049 | — | TORQUE TEAM B83 | — | 578/612 | 13AV1020 | — | 244/258 |
| 065-00621-014 | — | — | TORQUE TEAM B85 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00621-014 | 104.237 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00621-015 | 105.050 | — | TORQUE TEAM B83 | — | 578/612 | 13AV1000 | — | 244/258 |
| 065-00621-016 | — | — | TORQUE TEAM B86 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00621-017 | 104.401 | — | TORQUE TEAM B89 | — | 595/630 | AVX13X1100 | — | 244/258 |
| 065-00622-000 | — | — | TORQUE TEAM 2/BX84 | — | — | 13AV965 | — | — |
| 065-00622-001 | — | — | — | — | — | — | — | — |
| 065-00623-002 | — | — | TORQUE TEAM 2/BX85 | 30 | 703 | 13AV990 | 75 | 105 |
| 065-00623-004 | — | — | TORQUE TEAM 2/BX86 | 25 | 541 | 2X13X1550 | 35 | 256 |
| 065-00623-005 | — | — | TORQUE TEAM 2/BX85 | 29 | 561 | 2X13X1500 | 39 | 313 |
| 065-00623-006 | — | — | TORQUE TEAM 2/BX82 | 31 | 610 | 2X13AVX1475 | 40 | 327 |
| 065-00623-007 | — | — | TORQUE TEAM 2/BX83 | 30 | 882 | 13AV1045 | 75 | 209 |
| 065-00623-008 | — | — | TORQUE TEAM 2/BX83 | 30 | 726 | 13AV990 | 118 | 212 |
| 065-00623-009 | — | — | TORQUE TEAM 2/BX85 | 25 | 541 | 13AV965 | 118 | 212 |
| 065-00623-010 | 104.112 | — | TORQUE TEAM B87 | — | 595/630 | 13AV1000 | — | 246/260 |
| 065-00623-011 | 103.624 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 240/255 |
| 065-00623-014 | 104.067 | — | TORQUE TEAM B87 | — | 595/630 | TORQUE TEAM A60 | — | 289/306 |
| 065-00623-015 | 104.053 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00623-016 | 103.914 | — | TORQUE TEAM B85 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00623-017 | 103.900 | — | TORQUE TEAM B87 | — | 595/630 | 13AV0950 | — | 246/260 |
| 065-00624-001 | — | — | TORQUE TEAM 2/BX85 | 30 | 904 | 2X13AVX1425 | 51 | 412 |
| 065-00624-002 | — | — | TORQUE TEAM 2/BX87 | 28 | 874 | TORQUE TEAM 2/AX59 | 47 | 413 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00624-003 | — | — | TORQUE TEAM 2/BX85 | 30 | 904 | 2X13AVX1475 | 48 | 408 |
| 065-00624-004 | — | — | TORQUE TEAM 2/BX85 | 26 | 539 | 13AV1045 | 48 | 408 |
| 065-00625-000 | — | — | TORQUE TEAM 2/BX81 | 25 | 541 | 13AV1045 | 35 | 256 |
| 065-00625-001 | — | — | TORQUE TEAM 2/BX83 | 28 | 833 | 13AV990 | 118 | 212 |
| 065-00625-005 | — | — | TORQUE TEAM 2/BX81 | 28 | 833 | TORQUE TEAM 2/AX59 | 47 | 413 |
| 065-00625-006 | — | — | TORQUE TEAM 2/BX81 | 30 | 859 | 2X13AVX1475 | 48 | 408 |
| 065-00626-001 | — | — | TORQUE TEAM 2/BX86 | 29 | 880 | TORQUE TEAM 2/AX59 | 47 | 413 |
| 065-00626-002 | — | — | TORQUE TEAM 2/BX82 | 30 | 846 | 2X13AVX1475 | 48 | 408 |
| 065-00626-003 | — | — | TORQUE TEAM 2/BX85 | 29 | 561 | 13AV990 | 87 | 209 |
| 065-00626-004 | — | — | TORQUE TEAM 2/BX82 | 30 | 882 | 13AV1045 | 75 | 209 |
| 065-00626-005 | 104.268 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00630-000 | — | — | TORQUE TEAM 2/BX87 | 33 | 575 | 2X13AVX1500 | 43 | 277 |
| 065-00630-001 | — | — | TORQUE TEAM 2/BX85 | 32 | 572 | 2X13AVX1475 | 43 | 277 |
| 065-00630-002 | — | — | TORQUE TEAM 2/BX85 | 25 | 566 | 13AV1045 | 118 | 212 |
| 065-00630-003 | — | — | TORQUE TEAM 2/BX87 | 28 | 583 | 13AV1020 | 118 | 212 |
| 065-00630-004 | — | — | TORQUE TEAM 2/BX85 | 32 | 572 | 2X13AVX1475 | 47 | 413 |
| 065-00630-005 | — | — | TORQUE TEAM 2/BX87 | 33 | 575 | 2X13AVX1500 | 47 | 413 |
| 065-00631-000 | — | — | TORQUE TEAM 2/BX97 | 22 | 781 | 13AV1090 | 74 | 110 |
| 065-00631-001 | — | — | TORQUE TEAM 2/BX97 | 27 | 781 | 13AV1090 | 74 | 110 |
| 065-00631-002 | — | — | TORQUE TEAM 2/BX97 | 27 | 779 | 13AV1090 | 74 | 110 |
| 065-00631-003 | — | — | TORQUE TEAM 2/BX90 | 27 | 676 | 13AV1150 | 66 | 248 |
| 065-00631-004 | — | — | TORQUE TEAM 2/BX93 | 28 | 588 | 13AV1150 | 59 | 207 |
| 065-00631-005 | 104.317 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00631-006 | 104.307 | — | TORQUE TEAM B84 | — | 595/630 | 13AV1045 | — | 244/258 |
| 065-00631-007 | 104.347 | — | TORQUE TEAM B84 | — | 561/594 | 13AV1100 | — | 287/304 |
| 065-00631-008 | 104.372 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00631-009 | 104.376 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00631-010 | 104.382 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1100 | — | 287/304 |
| 065-00631-011 | 104.387 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1100 | — | 287/304 |
| 065-00632-001 | — | — | — | — | — | — | — | — |
| 065-00632-002 | — | — | B112 MEGADYNE/JASON | 20,5 | 903 | 13AV1045 | 88,2 | 150 |
| 065-00632-003 | — | — | B112 MEGADYNE/JASON | 21 | 573 | 13AV1150 | 62 | 267 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00632-004 | 104.293 | — | TORQUE TEAM B66/67 | — | 561/594 | 13AV1150 | — | 246/260 |
| 065-00632-005 | 104.333 | — | TORQUE TEAM B68 | — | 561/594 | 2X13X1120 | — | 246/260 |
| 065-00632-006 | 104.340 | — | TORQUE TEAM B68 | — | 561/594 | 13AV1100 | — | 246/260 |
| 065-00632-007 | 104.284 | — | TORQUE TEAM B67 | — | 561/594 | 13AV1045 | — | 246/260 |
| 065-00632-008 | — | 050-0854208-000 | AVX 13X1150 A 1175 | — | 640 | 2BX-73 | — | 310 |
| 065-00632-009 | — | 050-0853108-002 | AVX 13X1150 A 1175 | — | 640 | 2BX-72 | — | 310 |
| 065-00633-000 | — | — | — | — | — | — | — | — |
| 065-00635-000 | 104.062 | — | TORQUE TEAM B85 | — | 595/630 | TORQUE TEAM A60 | — | 240/255 |
| 065-00636-001 | — | — | TORQUE TEAM 2/BX84 | 29 | 880 | TORQUE TEAM 2/AX55 | 39 | 338 |
| 065-00636-002 | — | — | TORQUE TEAM 2/BX83 | 27 | 553 | 13AV1020 | 39 | 338 |
| 065-00636-003 | — | — | TORQUE TEAM 2/BX84 | 29 | 880 | 13AV1020 | 39 | 338 |
| 065-00636-004 | — | — | TORQUE TEAM 2/BX85 | 27 | 553 | 13AV1020 | 39 | 338 |
| 065-00637-000 | — | — | — | — | — | — | — | — |
| 065-00637-001 | — | — | — | — | — | — | — | — |
| 065-00638-000 | — | — | — | — | — | — | — | — |
| 065-00638-001 | — | — | — | — | — | — | — | — |
| 065-00638-002 | — | — | — | — | — | — | — | — |
| 065-00638-003 | — | — | POLY "V" 6PK 2745 | — | — | POLY "V" 6PK 1315 | — | — |
| 065-00639-000 | — | — | TORQUE TEAM 2/BX83 | — | — | 13AV1045 | — | — |
| 065-00639-001 | — | — | TORQUE TEAM 2/BX86 | 29 | 880 | 13AV990 | 118 | 212 |
| 065-00640-000 | — | — | TORQUE TEAM 2/BX58 | 31 | 819 | 13AV990 | 118 | 212 |
| 065-00640-001 | — | — | TORQUE TEAM 2/BX58 | 31 | 819 | 13AV990 | 118 | 212 |
| 065-00640-002 | — | — | TORQUE TEAM 2/BX104 | 32 | 657 | 13AV1150 | 46 | 232 |
| 065-00640-003 | 104.289 | — | TORQUE TEAM B100 | — | 595/630 | AVX13x1020 | — | 244/258 |
| 065-00640-004 | 104.373 | — | TORQUE TEAM B100 | — | 595/630 | AVX13x1120 | — | 287/304 |
| 065-00640-005 | 104.378 | — | TORQUE TEAM B98 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00640-006 | 104.393 | — | TORQUE TEAM B100 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00641-000 | — | — | TORQUE TEAM 2/BX86 | 29 | 880 | 13AV965 | 118 | 150 |
| 065-00642-000 | — | — | TORQUE TEAM 2/BX58 | 31 | 819 | 13AV990 | 118 | 212 |
| 065-00643-000 | — | — | TORQUE TEAM 2/BX84 | 30 | 624 | 13AV990 | 87 | 134 |
| 065-00643-001 | — | — | TORQUE TEAM 2/BX82 | 30 | 624 | TORQUE FLEX AX40 | 87 | 134 |
| 065-00643-002 | — | — | TORQUE TEAM 2/BX84 | 29 | 583 | 13AV990 | 87 | 134 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00643-003 | 104.323 | — | TORQUE TEAM B83 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00643-004 | 104.329 | — | TORQUE TEAM B84 | — | 561/594 | AVX13X1045 | — | 244/258 |
| 065-00643-005 | 104.342 | — | TORQUE TEAM B82 | — | 561/594 | 13AV1060 | — | 244/258 |
| 065-00644-000 | — | — | TORQUE TEAM 2/BX85 | 29 | 541 | 13AV1045 | 69 | 107 |
| 065-00644-001 | — | — | TORQUE TEAM 2/BX85 | 29 | 541 | 13AV1045 | 69 | 107 |
| 065-00644-002 | 104.282 | — | TORQUE TEAM B87 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00645-000 | 103.734 | — | POLY-V 6PK1530 | — | — | — | — | — |
| 065-00645-001 | 104.299 | — | | — | — | TORQUE TEAM A60 | — | — |
| 065-00645-002 | — | 050-1350600-000 | AVX 2X13X1525 A 1550 | — | 510 | — | — | — |
| 065-00646-000 | 104.163 | — | TORQUE TEAM B98 | — | 595/630 | 13AV1060 | — | 246/260 |
| 065-00647-000 | 104.190 | — | TORQUE TEAM B83 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00648-000 | — | — | TORQUE TEAM 2/BX85 | 25 | 541 | 13AV965 | 118 | 212 |
| 065-00648-001 | — | — | TORQUE TEAM 2/BX83 | 27 | 573 | 13AV990 | 118 | 212 |
| 065-00648-002 | — | — | TORQUE TEAM 2/BX83 | 27 | 573 | 13AV1045 | 118 | 212 |
| 065-00649-000 | — | — | TORQUE TEAM 2/BX80 | 31 | 716 | 13AV1045 | 90 | 153 |
| 065-00650-000 | — | — | TORQUE TEAM 2/BX82 | 24 | 677 | 13AV1045 | 104 | 270 |
| 065-00650-001 | — | — | TORQUE TEAM 2/BX85 | 27 | 573 | — | — | — |
| 065-00650-002 | — | — | TORQUE TEAM 2/BX85 | 27 | 573 | 13AV1020 | 104 | 270 |
| 065-00650-003 | 104.337 | — | TORQUE TEAM B83 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00650-004 | 104.203 | — | TORQUE TEAM B84 | — | 561/594 | — | — | — |
| 065-00650-005 | 104.338 | — | TORQUE TEAM B84 | — | 561/594 | AVX13x1020 | — | 244/258 |
| 065-00651-000 | — | — | TORQUE TEAM 2/AVX13X1675 | 37 | 364 | — | — | — |
| 065-00651-001 | 104.197 | — | 2X13X1570 | — | 280/297 | — | — | — |
| 065-00652-000 | — | — | TORQUE TEAM 2/AX68 | 36 | 379 | — | — | — |
| 065-00652-001 | — | — | 2X13AVX1750 | 36 | 347 | — | — | — |
| 065-00652-002 | — | — | 2X13AVX1750 | 36 | 347 | — | — | — |
| 065-00653-000 | 104.208 | — | TORQUE TEAM B91 | — | 594/630 | 13AV1045 | — | 240/255 |
| 065-00654-000 | 104.214 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1020 | — | 246/260 |
| 065-00655-000 | 104.216 | — | TORQUE TEAM B86 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00655-001 | 104.223 | — | TORQUE TEAM B87 | — | 595/630 | 13AV0950 | — | 244/258 |
| 065-00655-002 | 104.221 | — | TORQUE TEAM B86 | — | — | 13AV1020 | — | 244/258 |
| 065-00656-000 | — | — | TORQUE TEAM 2/BX87 | 28 | 598 | 13AV1045 | 118 | 274 |

| Código Base Valeo | Código Base Tecno Suporte | Código Base Meister | Correia motor/compressor | Tensão | | Correia compressor/alternador | Tensão | |
|-------------------|---------------------------|---------------------|--------------------------|--------|---------|-------------------------------|--------|---------|
| | | | | HZ | N | | HZ | N |
| 065-00656-001 | — | — | TORQUE TEAM 2/BX84 | 32 | 602 | 13AV1045 | 74 | 277 |
| 065-00656-002 | 104.313 | — | TORQUE TEAM B89 | — | 561/594 | — | — | — |
| 065-00656-003 | 104.314 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1150 | — | 287/304 |
| 065-00656-004 | 104.315 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1135 | — | 287/304 |
| 065-00656-005 | 104.316 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1135 | — | 287/304 |
| 065-00656-006 | 104.322 | — | TORQUE TEAM B90 | — | 561/594 | 13AV1020 | — | 244/258 |
| 065-00656-007 | 104.335 | — | TORQUE TEAM B86 | — | 561/594 | AVX13x1045 | — | 244/258 |
| 065-00656-008 | 104.318 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00656-009 | 104.344 | — | TORQUE TEAM B86 | — | 561/594 | 13AV1120 | — | 287/304 |
| 065-00656-010 | 104.341 | — | TORQUE TEAM B86 | — | 561/594 | — | — | — |
| 065-00656-011 | 104.351 | — | TORQUE TEAM B90 | — | 561/594 | 13AV1100 | — | 287/304 |
| 065-00656-012 | 104.374 | — | TORQUE TEAM B89 | — | 561/594 | 13AV1045 | — | 244/258 |
| 065-00657-000 | 104.243 | — | TORQUE TEAM B98 | — | 595/630 | 13AV1020 | — | 244/258 |
| 065-00658-000 | 103.088 | — | TORQUE TEAM B54 | — | 500/550 | — | — | — |
| 065-00659-000 | 104.260 | — | TORQUE TEAM B86 | — | 595/630 | AVX13X1020 | — | 244/258 |
| 065-00660-000 | 104.261 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00660-001 | 104.268 | — | TORQUE TEAM B86 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00663-000 | 104.266 | — | TORQUE TEAM B84 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00663-001 | 104.270 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00663-002 | 104.262 | — | TORQUE TEAM B84 | — | 595/630 | 13AV0975 | — | 244/258 |
| 065-00664-000 | 104.301 | — | TORQUE TEAM B84 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00664-001 | 104.303 | — | TORQUE TEAM B85 | — | 595/630 | 13AV1000 | — | 244/258 |
| 065-00665-000 | 104.014 | — | 2X13X1610 | — | — | — | — | — |
| 065-00665-001 | — | 050-1350300-000 | AVX2X13X1600 | — | 530 | — | — | — |
| 065-00668-000 | 104.352 | — | TORQUE TEAM B85 | — | 578/612 | 13AV1020 | — | 244/258 |
| 065-00668-001 | 104.358 | — | TORQUE TEAM B85 | — | 578/612 | — | — | — |
| 065-00669-000 | 104.379 | — | POLY-V 6PK1980 | — | — | — | — | — |
| 065-00670-000 | — | 050-1391408-003 | 2BX-76 | — | 680 | AVX 13X1025 A 1050 | — | 310 |
| 065-00671-000 | 104.282 | — | TORQUE TEAM B87 | — | 595/630 | AVX13x1020 | — | 244/258 |

Revisão: 31/01/2024 Responsável: RCosta